










Manual








Group hutch - 6










Parts

Nr	Count	Drawing
1	1x	
2	2x	
3	41x	M8 x 30 
4	52x	M8 
5	40x	Nut M8 
6	1x	
7	1x	
8	2x	M8 x 30 







Parts

Nr	Count	Drawing
9	2x	
10	3x	
11	7x	Locknut M8 
12	1x	
13	1x	
14	2x	
15	12x	M10 x 40 






Parts

Nr	Count	Drawing
16	24x	M10 
17	28x	Nut M10 
18	1x	
19	5x	
20	16x	M10 x 45 
21	1x	
22	1x	



Parts

Nr	Count	Drawing
23	2x	
24	8x	
25	1x	
26	1x	
27	4x	M8x45 
28	2x	
29	2x	




Parts

Nr	Count	Drawing
30	1x	
31	8x	
32	2x	
33	6x	
34	1x	

1



2






3

1


Ø8
2x

7




2x



4





DETAIL C







Inside




5



6





7




DETAIL A

Low




High

8





Outside

A





DETAIL A

9





DETAIL A

10




11




2x


DETAIL A





DETAIL A



12





13




DETAIL A

14





DETAIL A

15



16



DETAIL A